Path ID **Planned Action Route Description** Paved private road – No action Ockley Lane to Burgess Hill **1K** Water Tower (FP) Wellhouse Lane (FP) Paved private road – No action 2K Ockley Lane South to Majority of Bridleway rebuilt in 2017 – in very good condition **3**K Oldlands Mill (BW) Adjacent to middle part of Footpath steps replaced in 2017 – No further action proposed as **4**K Path 3K (FP) Users would use Path 3K in preference during wet weather. East section is firm walking West section gets boggy in winter. Friars Oak Pub east across 5K Lies on two sites with planning permission for housing S106 railway to Ockley Manor requires tunnel under railway – potential for upgrade to (FP) bridleway – pursue with WSCC and developers at detailed planning stage. Paved private road – No Action **Ockley Manor to Oldlands 6**K Mill (BW) Woodsland Road west Paved footpath resurfaced in 2019 which included removal of 7K under railway to Little flooded depression – No Action Copse Road (FP) Thatched Inn SE toward Heavily used path with fenced sections – Monday Group asked to **8**K Ditchling (FP) improve worst parts with hardcore - Ongoing at Jan 2021 Silverdale north to Path 8K North Section gets boggy and needs hard surface -Landowner has **9K** near Damian Way (FP) not agreed to Monday Group work in the past. Fir Tree Way NW across Diagonal route across Park creates issues when holding ticketed **10K** Adastra Park to Grand events. – Consider rerouting path to existing E-W path across Park- discuss with WSCC. Avenue (FP) Woodsland Road North to Paved private road which provides walking and cycle access to **11K** Path 5K at Woodside Clayton Mills – Upgrade to Bridleway/Cycleway required as part Grange (FP) of future housing development North of Path 5K Lodge Lane SW toward Half Fenced Section nearest Lodge Lane was improved with hard 12K Way House – becomes surface in 2016 – remainder is in open countryside. Action- Area Path 18C (FP) approaching stream is slippery and needs hard surface. New Road SW toward Little used path because it ends on Fast road with no pavements. 13K Clayton – becomes Path 19C (FP) Lodge Lane (South end) SW Path in Open Countryside with normal wet weather issues – **14K** to Underhill Lane (FP) Review as some sections are boggy Underhill Lane to Keymer Steep climb with gravelly surface on North section – generally dry **15K** Post(on South Downs Way) and useable all year. -No Action continuing SSW toward Line of PROW to be reviewed by Les/lan in 2021 Chattri Memorial becomes 21Py (BW) Link Path from Car Park on Gravelly surface makes this useable in winter – No Action **16K** Underhill Lane in Ditchling Parish connecting to North section of Path 15K (FP) Part of South Downs Way and fully maintained by SDNP and Section of SDW from **17K** Keymer Post West toward upgraded in 2018 Jack and Jill Windmills becomes 17C (FP)

East side of Parish - (historically Keymer Parish)

18K	Link Path from 15K (Section S of SDW) South to Parish Boundary and toward Standen Farm (FP)	PROW to be reviewed by Les/Ian in 2021
19K	Mackie Avenue to Path 21K behind gardens of Grand Avenue (FP)	Little used path with sections of poor-quality surface. Could benefit from levelling but low usage doesn't justify hard surface. Discuss with Clayton Mills Management Committee
20K	Ockley Lane to Fir Tree Way behind gardens of The Quadrant and along Clerks Acre (FP)	Poor quality surface particularly at east end – otherwise ok for the light use it gets. PROW to be reviewed by Les/Ian in 2021
21K	Woodsland Road to Grand Ave behind Gardens of Queens Drive (FP)	Moderately heavy use as a link route – surface is rutted and overgrown in places – would benefit from widening levelling and a hard surface for all year use. Priority for upgrade
22K	Orchard Lane along West side of Adastra Park (FP)	Private Road maintained by Parish Council and other owners – would make a good traffic free cycle route to village centre and schools avoiding Grand Avenue. Discuss with WSCC
23K	Link Path from The Close to Path 22K (FP)	Little used path with sections of poor-quality surface. No action
24K	Link Section From Damian Way to Path 9K (FP)	Paved Path – No Action
25K	Short Section of SDW from Keymer Post East toward Ditchling Beacon (FP)	Part of South Downs Way and fully maintained by SDNP and upgraded in 2018

West side of Parish – (historically Clayton Parish)

Path ID	Route Description	Planned Action
1C	Now part of Burgess Hill	Outside the Parish
2C	Tesco Roundabout to Scotches Farm (FP)	Part of Burgess Hill Green Circle – managed by BHTC
2C-1	Short section - Scotches Farm to The Paddocks (BW)	Part of Burgess Hill Green Circle – Landowner is BHTC
3C	Jane Murray Way to Hammonds Mill Farm (FP)	North section is part of Burgess Hill Green Circle South section recently fenced by Landowner – Consider for upgrade to Bridleway - Discuss with WSCC
4C	Link Path from Path 3C to Path 6C adjacent to Hammonds Mill Farm (FP)	Recently fenced by Landowner – Consider for upgrade to Bridleway - Discuss with WSCC
4C-1	Hammonds Mill south to Path 4C-2 (FP)	Consider for upgrade to Bridleway - Discuss with WSCC
4C-2	Friars Oak House west to Path 8C then North to Path 4C-1 then west towards Hurst College (BW)	Generally good except in wet weather – Proposed upgrade to hard surface with funds from Golf Course S106 funds – Research funding
5C	Link from 2C-1 to 57Hu outside The Paddocks	Path is on paved Private Road – No Action

5C-1Along Scotches Farm east boundary then SW toward Hurst College – becomes 78 Hu (FP)PROW to be reviewed by Les/Ian in 20215C-2Link Path from 5C-1 toPROW to be reviewed by Les/Ian in 2021	
Hurst College – becomes 78 Hu (FP)	
78 Hu (FP)	
Hammonds Mill Farm (FP)	
6C London Road (just S of Path in Open Countryside with normal wet weather i entrance to Hammonds Action	ssues – No
Mill Farm) west beside	
stream towards Hurst	
College – becomes 56-2Hu	
(FP)	
7C From Junction of Path 4C-2 Path in Open Countryside with normal wet weather i	sues hut
and Path 8C NW towards generally good surface – No Action	
Hurst College (FP)	
8C Whole of Belmont Lane Bridleway on paved private road with northern section	<mark>on on</mark>
through Clayton Wickham upgraded hard surface. Northern section requires	
then North to Junction of brushing/cleaning to remove several years of loose m	naterial
Path 4C-2 and Path 7C which causes muddy patches on an otherwise good s	
(BW)	
9C Friars Oak Pub West to Currently affected by housing development – Wester	n section
Belmont Lane (FP) will need upgrading on completion of the developme	nt to carry
extra users and consideration of upgrade to Bridlewa	<mark>y to carry</mark>
cycle way towards Hurstpierpoint	
10C London Road (Saxon Mills) Currently affected by housing development – NW see	tion is in
NW to Path 9C Open Countryside with normal wet weather issues –	
11C Crossways Lane to Path Northern section affected by flooding. In 2019 a shor	
13C just north of adjacent to a lake was improved with a hard surface.	
Coldharbour Farm (FP) upgrading has been agreed with landowner – awaitin	g additional
quotes prior to approval by Council.	
11C-1 Link Path in field just north	ssues – No
of Coldharbour Farm (FP) Action	
12C Brighton Road (N of Jack & Low usage path in Open Countryside with normal we issues and Astian	t weather
Jill Pub) to Path 28C at issues – No Action Coldharbour Farm (FP)	
	weather
13C Brighton Road (ClaytonWell used path in Open Countryside with normal wetBurial Ground) West thenissues. A short section to west of junction with 11C-1	
South to Path12C at wood and is severely affected by protruding tree roo	
Coldharbour Farm (FP) improvement with WSCC.	
14C Keymer Road (Rail Bridge) Well used Path linking Hassocks to Clayton. Many sec	tions are
South to A273 at Clayton paved but now in poor state. Planned improvements	
(known as Cinder Path) (FP) and SDNP were proposed but are currently stalled.	
for update from County Councillor	
15C Clayton Rec to Mill Lane & Well used Bridleway giving traffic-free access to the M	Vindmills
SDW by Jack Windmill (BW) and SDW. – Managed by SDNP and upgraded in2018	
15-1C Link into Jack and Jill Managed by SDNP	
Windmill car park (FP)	
16C Path adjacent to mid- Managed by SDNP	
section of Path 15C	
17C Mill Lane (at Jill Mill) East Managed by SDNP – Improved to a good standard in	2018
toward Keymer Post –	
becomes 17K (BW)	

100	New Road at Path 21C to	Follows existing track then crosses well drained field. Consider
18C	Half way House then NE to	upgrade to Bridleway as part of New Path Project
	become Path 12K	apprade to bridleway as part of New Fath Floget
19C	Spring Lane NE to New	Little used path because it ends on Fast road with no pavements.
190	Road - becomes Path 13K	Entre used path because it entry off fast foud with no pavements.
	(FP)	
20C	Underhill Lane (Pump	Steep access on track then well drained field. – Managed by
200	House) to Bridleway 15C	SDNP PROW to be reviewed by Les/Ian in 2021
	(FP)	
21C	New Road at Path 18C to	Well Used Good condition track and then roadway - No Action
	Spring Lane Clayton (BW)	
22C	No Record on Database	
23C	Keymer Road to Clayton	Northern section is a boggy and little used path. Western Section
250	Avenue (west end) then to	is well used and gets muddy in winter. As 14C is paved upgrading
	Path 14C (FP)	the western section of this path would be beneficial
24C	Keymer Road Mini	Paved footpath – No Action
240	Roundabout to No 9	
	Clayton Avenue (FP)	
25C	Link Path West end of	Paved footpath – No Action
230	Ockenden Way to Path 14C	
	(FP)	
26C	Linking Downsview Road to	Paved footpath – No Action
	Parklands Road in Hassocks	
	(FP)	
27C	Butchers Wood at Path 14C	Well used path in Open Countryside with normal wet weather
	to Half Way House (FP)	issues. A short section adjacent to Herring Stream floods and
		improvements would be beneficial – however flood control and a
		raised section of walking route make this a potentially costly
		improvement. Discuss with HKD and Flood Group
27-1C	Misty Bridge at Path 14C to	Well used path in Open Countryside with normal wet weather
	Path 27C at Woodbine	<mark>issues.</mark>
	Cottage (FP)	
28C	Coldharbour Farm to New	Paved footpath – No Action
	Way Lane (FP)	
29C	A273 at Clayton Burial	Majority is hard surface although a few boggy sections may need
	Ground to Misty Bridge	attention – Review for short term solution
	(FP)	Outside Devich
30C	Now part of Burgess Hill	Outside Parish
3739	Tesco Roundabout west to	Part of Burgess Hill Green Circle – managed by BHTC
	Parish Boundary	
3741	Tesco Roundabout east to	Part of Burgess Hill Green Circle – managed by BHTC
	Hammonds Ridge	
	Roundabout	
3742	Link Path at Hammonds	Part of Burgess Hill Green Circle – managed by BHTC
	Ridge Roundabout	
3743	Link Path at Hammonds	Part of Burgess Hill Green Circle – managed by BHTC
	Ridge Roundabout	

Projects for Upgrade of Heavily used PROW routes

Priority Designation: Numbered from P1 – *Highest Priority* to P20 – *Lowest Priority*

Ease of Delivery: Easiest Moderate Hardest

Project Description	Action and Progress
Improved Access to SDNP from Village	Project Brief to be prepared for G+E Committee
Centre and Keymer to SDNP – This project	
has 2 elements: a) a new Bridleway linking	
Parklands Road to existing Bridleway 21C	
at Spring Lane Clayton and b) a new	
bridleway on east side of Lodge Lane from	
pavement end southward to crossing point	
at New Road.	
Addition of path from 24K due east to join	Discuss with WSCC prior to making an application.
8K at Ditchling boundary to Definitive	
PROW map – existing well used path which	
is shown on OS maps was recently fenced	
by landowner.	
Extension of cycle route and footpath	Research required prior to Project Brief.
along west side of Railway from South	
Bank to Jack and Jill Pub with alternative	
routes considered.	
Safe cycle route to Clayton	Research required prior to Project Brief.
Review PROWS with heavy use to upgrade	
to hard surface (rural style)	
Upgrade Path 5K to bridleway to coincide	Discuss with WSCC prior to engaging with developers /
with new tunnel under railway and	landowners at detailed planning stage – Funding
upgrade to allow all weather use and cycle	options may be available from Central Government via
route	WSCC or from developers
Divert path 10K in Adastra Park to allow	Discuss with WSCC to confirm whether charging applies
ticketed events to be held in North Field	for the diversion. If chargeable then current costs are
without having to apply for temporary	approx. £1,800. Approval of Parish Council as the
stoppage orders	landowner will be required.
Path 21K behind Grand Ave requires	Quote acquired in 2019 – WSCC approached for funds
upgrading for all weather use as provides a	but unable to help. Obtain further quotes and look for
well-used link.	S106 funding or WSCC help.
Path 4C-2 is heavily used linking Hurst	Research into s106 funding required prior to project
College to London Road A273 near Friars	proposal
Oak.	
Extend Belmont Lane Bridleway north to	Existing Bridleway 8C is in good condition and the link
Burgess Hill Green Circle to provide	on Bridleway 4C-2 is proposed for upgrading. The link
through route for recreational use.	northward is currently on Footpaths 3C, 4C and 4C-1
	requires upgrade to Bridleway to create through link.
	Will need discussion with Landowners and WSCC to
	enable link prior to Project Proposal
Upgrade Path 9C to Bridleway to link from	Discuss with WSCC and Landowners prior to project
Friars Oak and new Golf Course	proposal
development west to Belmont Lane	
Further upgrading of Path 11C	Northern section affected by flooding was upgraded in
	2019. Further upgrading has been agreed with

	landowner – awaiting additional quotes prior to approval by Council.
Upgrade part of Path 23C linking Clayton Avenue to Path 14C (Cinder Path)	Short section – subject to G+E agreement – to use HPC footpath funding.
Path 27C outside Woodbine Cottage suffers severe flooding in winter and requires creation of a dry route.	A short section crossing the Herring Stream floods and requires upgrading. Potential site for flood control and need for a raised section of walking route make this a potentially costly improvement. Step1 - Discuss with HKD Transition and Flood Group. Step2 – Potential <i>Operation Watershed</i> funding
Local Review of Path Network by Ian / Les	Due during latter part of 2021.
Discuss Path improvements with WSCC	Prepare detailed listing for discussion in Spring 2021. Arrange Zoom meeting with WSCC to discuss options funding a support in Landowner discussions.
Path 13C north of Coldharbour Farm is dangerous to use due to tree roots	A short section to west of junction with 11C-1 enters a wood and is severely affected by protruding tree roots – Discuss improvement with WSCC